

Oakland Military Institute, College Preparatory Academy (1612590130617) | Inspected by Scott Bollander

#### **CATEGORY TOTALS AND RANKING** (round all calculations to two decimal places)

		А	. SYSTEMS		B. INTERIOR	C. CLEA	NLINESS	D. ELECTRICAL	E. RESTR FOUNT		F. S	AFETY	G. STRUC	TURAL	H. EXTERNAL	
TOTAL NUMBER OF AREAS	CATEGORY TOTALS	GAS LEAKS	MECH/HV AC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATES/FENCES
EVALUATED	Number of "OK"s:	41	41	41	41	41	41	41	13	24	41	41	41	41	3	41
	Number of "D"s:	0	0	0	0	0	0	0	0	0 0		0	0	0	0	0
41	Number of "X"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
41	Number of N/As:	0	0	0	0	0	0	0	28	17	0	0	0	0	38	0
Percent of Sy Number of "Oh (Total Areas - '		100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%
Total Percent (average of ab			100.00%		100.00%	100.	100.00%		100.00%		100.00%		100.00%		100.00%	
Rank GOOD = 90%-1 FAIR = 75%-89. POOR = 0%-74.	99%	EX	EMPLAR'	Y	EXEMPL ARY	EXEMI	PLARY	EXEMPLARY	EXEMP	EXEMPLARY		MPLARY	EXEMPLARY		EXEMPLARY	
		OVERALL F		RCENTAGE (	OF 8 CATEGO	RIES ABOVE			100.0	00%	sc	HOOL RAT	ING**		EXEMPLARY	

<sup>\*\*</sup>For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	RATING	DESCRIPTION
99%-100%	EXEMPLARY	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.
90%-98.99%	GOOD	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.
75.%-89.99%	FAIR	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.
0%-74.99%	POOR	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.



ID	Building / Area Name	Estimated Square Footage	GAS LEAKS	МЕСН/НVАС	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES	COMMENTS:
1	Main Entrance		ОК	ок	ок	ок	ок	ок	ок	NA	NA	ок	ок	ОК	ок	NA	ОК	
2	Vlain Office		ок	ОК	ок	ОК	ок	ОК	ОК	NA	NA	ок	ок	ОК	ОК	NA	ОК	
	Multi Purpose Room		ок	ок	ок	ок	ок	ок	ок	NA	ок	ок	ок	ок	ок	NA	ок	
	Staff Restroom by multi purpose room		ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	NA	ОК	
5	Playground		ок	ок	ок	ок	ок	ок	ок	NA	ок	ок	ок	ок	ок	ок	ОК	
6	Athletic Field		ок	ок	ок	ок	ок	ок	ок	NA	NA	ок	ок	ок	ок	ок	ОК	
7	Staff restroom by 16		ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	NA	ОК	
8	Classroom 15	1000	ок	ок	ок	ок	ок	ок	ок	NA	ок	ок	ок	ок	ок	ок	ок	
9	Classroom 17	1000	ок	ок	ок	ОК	ок	ок	ок	NA	ок	ок	ок	ок	ок	NA	ок	
	All gender Restroom by 16		ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	NA	ок	
11	Library	1000	ок	ок	ок	ок	ок	ок	ок	NA	NA	ок	ок	ок	ок	NA	ок	
12	Classroom P21	1000	ок	ок	ок	ок	ок	ок	ок	NA	ок	ок	ок	ок	ок	NA	ОК	
13	Classroom P22	1000	ок	ок	ок	ок	ок	ок	ок	NA	ок	ок	ок	ок	ок	NA	ок	
14	Classroom P23	1000	ок	ок	ок	ок	ок	ок	ОК	NA	NA	ОК	ок	ОК	ок	NA	ок	



ID	Building / Area Name	Estimated Square Footage	GAS LEAKS	МЕСН/НVАС	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES	COMMENTS:
15	Classroom P26	1000	ок	ок	ок	ок	ок	ОК	ок	NA	NA	ок	ок	ок	ОК	NA	ок	
	Boys Restroom by P22		ок	ок	ок	ОК	ок	ОК	ок	ОК	ок	ок	ОК	ОК	ОК	NA	ок	
	Girls restroom by P22		ок	ок	ок	ОК	ок	ОК	ок	ОК	ок	ок	ок	ОК	ОК	NA	ок	
18	Classroom P28	1000	ок	ок	ок	ок	ок	ОК	ок	NA	NA	ок	ок	ок	ок	NA	ок	
19	Classroom P27	1000	ок	ок	ок	ок	ок	ОК	ок	NA	NA	ок	ок	ок	ок	NA	ок	
20	Classroom C101	1000	ок	ок	ок	ок	ок	ОК	ок	NA	NA	ок	ок	ок	ок	NA	ок	
21	Classroom C102	1000	ок	ок	ок	ОК	ок	ОК	ок	NA	NA	ок	ок	ок	ок	NA	ок	
22	Classroom C103	1000	ок	ок	ок	ок	ок	ОК	ок	NA	NA	ок	ок	ок	ок	NA	ок	
23	Classroom C203	1000	ок	ок	ок	ок	ок	ОК	ок	NA	NA	ок	ок	ок	ок	NA	ок	
24	Classroom C202	1000	ок	ок	ок	ок	ок	ок	ок	NA	ок	ок	ок	ок	ок	NA	ок	
25	Classroom B101	1000	ок	ок	ок	ок	ок	ок	ок	NA	NA	ок	ок	ок	ок	NA	ок	
26	Classroom B102	1000	ок	ок	ок	ОК	ОК	ОК	ОК	NA	ок	ок	ок	ОК	ОК	NA	ок	
27	Classroom B103	1000	ок	ок	ок	ОК	ОК	ОК	ОК	NA	NA	ок	ОК	ОК	ОК	NA	ок	
28	Classroom B104	1000	ок	ок	ок	ок	ок	ок	ок	NA	NA	ок	ок	ок	ок	NA	ок	



ID	Building / Area Name	Estimated Square Footage	GAS LEAKS	МЕСН/НVАС	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES	COMMENTS:
29	Classroom B105	1000	ОК	ОК	ОК	ОК	ОК	ОК	ОК	NA	NA	ОК	ОК	ОК	ОК	NA	ОК	
	Boys Restroom B-wing 1st floor		ок	ок	ок	ОК	ок	ок	ок	ОК	ок	ОК	ок	ок	ок	NA	ок	
	Girls Restroom B-wing 1st floor		ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	NA	ок	
	All gender restroom B-wing 1st floor		ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	NA	ок	
	Boys Restroom B-wing 2nd floor		ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	NA	ок	
	Girls Restroom B-wing 2nd floor		ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	NA	ок	
	ADA restroom B-wing 2nd floor		ок	ок	ок	ОК	ок	ок	ок	ОК	ок	ОК	ок	ОК	ок	NA	ок	
36	Classroom B206	1000	ок	ок	ок	ОК	ок	ок	ок	NA	NA	ОК	ок	ок	ок	NA	ок	
37	Classroom B204	1000	ок	ок	ок	ОК	ок	ок	ок	NA	ок	ОК	ок	ОК	ок	NA	ок	
38	Classroom 14	1000	ок	ок	ок	ОК	ок	ок	ок	NA	ок	ОК	ок	ок	ок	NA	ок	
39	Classroom 4	1000	ок	ок	ок	ок	ок	ок	ок	NA	ок	ок	ок	ок	ок	NA	ок	
40	Boys restroom by 9		ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	NA	ок	
41	Girls Restroom by 9		ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ок	ОК	ок	NA	ок	