



Executive Team

Mildred S. Cunningham, President
& Chief Executive Officer

Dr. Raul Carranza, Superintendent

Matthew Brown, Chief Operating
Officer / Chief Financial Officer

Dr. Maria Pimienta, Assistant
Superintendent

Board of Directors

Lori Butler, Board Chairman

Dr. Sonali Tucker, Secretary

Kelvin Piazza, Member

James Lobdell, Member

Luz Castillo, Member

Spencer Burrows, Member

Austin Dragon, Member

Facilities Report – April 22, 2020

TEACH Prep 8505:

The new relocation of the wall has been completed. Also, the floors were waxed and site was checked for any needed repairs. The site is in good shape as of now. Also the new privacy fencing was installed on the back gate where the students play. The camera system is up and running.

TEACH Academy 10000:

Repairs have been made to leaks on both the MPR and main building . Also preventative maintenance has also been done to both buildings, cleaning out gutters and roof tops, and sealing to prevent any future leaks.

The remodel in the MPR has been completed of the room where the food service staff will be now be serving the meals for the students. Repairs are underway of a pipe from the second floor is broken and leaking to the first floor. Repairs should be completed this week. Also the privacy gate was installed in the front of the campus. The building was also checked to see if more repairs were needed. The camera system is up and running.

TEACH Academy 10045

The camera system is up and running. The privacy gate has been installed. Site has some leaks on some buildings that will be repaired.

TEACH Academy 1750

New drains have been installed that were requested by the city. Inspector is waiting for Impact the company that installed the bungalows, to produce all the paperwork and permits for the bungalows. So we can proceed to get the COO. Camera system is up and running.

TEACH Tech 10610:

Demolition has been started and is on hold until the structural engineer comes out, once he does then the permit can be requested to commence work on site once more.

TEACH Tech 10616:



General cleaning is being done and will be looked over to see if any repairs will be needed, but for now just mainly upkeep is being done. Camera system quote is going to be sent to fix issues.